



運輸署
Transport Department

By Fax (2187 2305)

本署檔號 Our Ref.: () in NR 25/31-5
來函檔號 Your Ref.:
電話 Tel.: 2399 2406
傳真 Fax.: 2381 3799

11 August 2014

Designing Hong Kong
Unit 7, 5/F, Eastern Harbour Centre
28 Hoi Chak Street
Quarry Bay

Dear Mr Zimmerman,

Missing and sub-standard pedestrian connections in the Tai Po District

Further to our acknowledgement on 24.7.2014, we have proceeded to study the situation and have the following findings:-

Ting Kok Road - Missing cycle path

Transport Department has commenced a consultancy study – “Improvements to Existing Cycle Tracks and Cycle Parking Facilities in New Towns and Review of Existing Bicycle Prohibition Zones - Feasibility Study”. The consultant will carry out a comprehensive investigation to identify locations at the existing cycle tracks and cycle parking facilities within the 9 new towns including Tai Po that need improvements and will devise traffic improvement schemes specific to the unique characteristic of each location. The missing cycle path at Ting Kok Road is identified in the assignment and being studied by the consultant.

Ting Tai Road - Missing crossing

Two existing subways are located on either side of the bus stop at Ting Tai Road. The two subways are at walkable distance from the bus stop which are easily and conveniently accessible to serve the same purpose. Transport Department has therefore no plan to provide an additional at-grade crossing facility.

If you have any further enquiries, please do not hesitate to contact us.

Yours sincerely,

(CHIU Chi-yiu)

for Commissioner for Transport

c.c.

Tai Po District Council Secretariat

Fax: 2654 6624

Internal
E/TP3

市區(九龍)及新界分區辦事處
Urban (Kln.) & NT Regional Offices
九龍聯運街三十號旺角政府合署七樓及八樓
7th & 8th Floor, Mong Kok Government Offices, 30 Lucan Wan Street, Kowloon.
圖文傳真 Fax No.: 2381 3799 (新界區) (NTRO) 2397 8046 (九龍市區) (UKRO)
網址 Web Site: <http://www.td.gov.hk>