

創建  
**Designing Hong Kong**  
邊度行路行? [www.MissingLinks.hk](http://www.MissingLinks.hk) 香港

YOUR REF: LPM/(GE/2013/27)/M10/300  
TD HR 183/161-4 (CW)

27 January, 2015

Mr LAU Ka Keung, Peter, JP  
Director of Highways  
Highways Department  
5<sup>th</sup> floor, Ho Man Tin Government Office,  
88 Chung Hau Street,  
Ho Man Tin, Kowloon

By post and email: [kklau@hyd.gov.hk](mailto:kklau@hyd.gov.hk)

**Re: Kennedy Road – 11SW-B/CR124 – Landslip Prevention – Hong Kong Island**

Dear Mr Lau,

Attached please find a reply from TD and CEDD regarding a missing section of the footpath and slope works along Kennedy Road. The location is identified in the attached response letters.

As stated by Transport Department, may we know the findings of the study for the provision of footpath along Kennedy Road? At the same time, has Highways Department advised slope owners (CEDD, HyD, etc) that slope works should include the provision of footpath where there is none at the toe or crest.

Please feel free to contact Mr. Leung at 3104-2766 or [denis@designinghongkong.com](mailto:denis@designinghongkong.com) if you have any enquiries.

Yours sincerely,

Paul Zimmerman, CEO of Designing Hong Kong

Encl. –CEDD's responses dated 6 August 2014  
TD's responses dated 28 August 2014

c.c. Commissioner of Transport (Attn: Mrs. Yeung Ho Poi Yan, Ingrid)  
Director of CEDD (Attn: Mr Hon Chi Keung)

Unit 7, 5/F, Eastern Harbour Centre, 28 Hoi Chak Street, Quarry Bay  
Tel: +852 3104 2765 Fax: +852 2187 2305