

創建 Designing HongKong 邊度冇路行? www.MissingLinks.hk 香港

"Missing Links" Report

香港灣仔告士打道 7 號

入境事務大樓 41 樓

運輸署署長 楊何蓓茵女士

郵寄及電郵: comr@td.gov.hk

新界屯門屯喜路 1 號

屯門政府合署 2 樓

屯門區區議會主席及議員

郵寄及電郵: tmdcadm@tmdc.had.gov.hk

屯門區區內不合標準和缺乏連接的行人路

敬啟者：

我們的活動「邊度冇路行」以改善香港行人路的連接性為目標，在過去一年，市民通過我們的網站 (www.missinglinks.hk) 報告了各區狹窄或不合標準的行人路和缺乏過路處的地點。

我們現將過去一年收集到的相關地點提供予運輸署及屯門區區議會，希望運輸署和屯門區區議會能共同改善有關的行人路和過路處，令屯門區的居民和遊客能夠享有安全而便捷的行人路。

隨信附上的照片和相關地點的列表。如有查詢，請聯絡創建香港梁先生 3104-2766 或 denis@designinghongkong.com。如有任何更新資訊，請隨時聯絡我們，以便告知相關的公眾。

此致

運輸署署長楊何蓓茵女士及屯門區區議會主席及議員 鈞鑒

司馬文
創建香港行政總裁

二零一四年七月十四日

隨函附上三個「邊到冇路行？」之詳細報告

創建 Designing Hong Kong 邊度冇路行? www.MissingLinks.hk 香港

"Missing Links" Report
14 July 2014

Mrs. YEUNG HO Poi Yan, Ingrid, JP
Commissioner for Transport
41/F, Immigration Tower
7 Gloucester Road, Wan Chai, Hong Kong

By post and email: comr@td.gov.hk

Chairman and Members of Tuen Mun District Council
2/F, Tuen Mun Government Offices,
1 Tuen Hi Road, Tuen Mun, N.T.

By post and email: tmdcadm@tmdc.had.gov.hk

Missing and sub-standard pedestrian connections in the Tuen Mun District

Dear Sirs and Madams

Our campaign 'Missing Links' began a year ago with the objective of improving pedestrian connections in Hong Kong. Via our website (www.missinglinks.hk), the public has identified locations where footpaths or crossings are either missing, narrow or sub-standard.

We are bringing the relevant locations identified during the first year to your attention and we would be grateful if Transport Department and the Tuen Mun District Council would work together to improve these pedestrian connections for the benefits of residents and visitors of the Tuen Mun District.

Enclosed please find a list of locations with photos and information. Please feel free to contact Mr. Leung at 3104-2766 or denis@designinghongkong.com if you have any questions. Keep us posted on the result so that we can inform the public accordingly.

Yours sincerely,

Paul Zimmerman, CEO of Designing Hong Kong

Encl. Maps and photos of 3 Missing Links

Unit 7, 5/F, Eastern Harbour Centre, 28 Hoi Chak Street, Quarry Bay,
Tel: +852 3104 2765 Fax: +852 2187 2305

創建 Designing HongKong 邊度冇路行? www.MissingLinks.hk 香港

"Missing Links" Report

1.

Location: The junction of Tuen Hing Road and Tuen Mun Heung Sze Wui Road

Category: Missing crossing

Suggestion: Provide signalised crossing

位置：屯興路與屯門鄉議會路交界

問題：缺乏過路處

建議：提供交通燈控制的過路處



Unit 7, 5/F, Eastern Harbour Centre, 28 Hoi Chak Street, Quarry Bay,
Tel: +852 3104 2765 Fax: +852 2187 2305

創建 Designing Hong Kong 邊度冇路行? www.MissingLinks.hk 香港

"Missing Links" Report

2.

Location: Hoi Wong Road bridge

Category: Missing footpath

Problem: There is no footpath connection between Hoi Wong Road and Tuen Mun pier

Suggestion: Provide footpath

位置：海皇路天橋

問題：狹窄行人路

詳情：沒有行人道路連接海皇路和屯門碼頭

建議：提供行人路



創建 Designing Hong Kong 邊度冇路行? www.MissingLinks.hk 香港

"Missing Links" Report

3.

Location: Tuen Mun Heung Sze Wui Road, alongside the Town Centre Station

Category: Missing Crossing

Problem: There is no at grade crossing. Also, there is no barrier free access for the footbridge

Suggestion: Add a standard crossing with a traffic island

位置： 沿著市中心輕鐵站，屯門鄉事會路

問題： 缺乏過路處

詳情： 缺乏地面過路處連接市中心輕鐵站及屯門市廣場，且行人天橋沒有升降機

建議： 提供標準過路處及安全島。

