

創建 Designing Hong Kong 邊度冇路行? www.MissingLinks.hk 香港

香港灣仔告士打道 7 號
入境事務大樓 41 樓
運輸署署長 楊何蓓茵女士

郵寄及電郵: comr@td.gov.hk

元朗橋樂坊 2 號
元朗政府合署 13 樓
元朗區區議會主席及議員

郵寄及電郵: yldcadm@yldc.had.gov.hk

元朗區區內不合標準和缺乏連接的行人路

敬啟者：

我們的活動「邊度冇路行」以改善香港行人路的連接性為目標，在過去一年，市民通過我們的網站 (www.missinglinks.hk) 報告了各區狹窄或不合標準的行人路和缺乏過路處的地點。

我們現將第二輪從民間收集到的相關地點提供予運輸署及元朗區區議會，希望運輸署和元朗區區議會能共同改善有關的行人路和過路處，令元朗區的居民和遊客能夠享有安全而便捷的行人路。

隨信附上的照片和相關地點的列表。如有查詢，請聯絡創建香港梁先生 3104-2766 或 denis@designinghongkong.com。如有任何更新資訊，請隨時聯絡我們，以便告知相關的公眾。

此致

運輸署署長楊何蓓茵女士及元朗區區議會主席及議員 鈞鑒

司馬文
創建香港行政總裁

二零一四年十二月十七日

隨函附上一個「邊到冇路行？」之詳細報告

創建 Designing Hong Kong 邊度冇路行? www.MissingLinks.hk 香港

17 December 2014

Mrs. YEUNG HO Poi Yan, Ingrid, JP
Commissioner for Transport
41/F, Immigration Tower
7 Gloucester Road, Wan Chai, Hong Kong

By post and email: comr@td.gov.hk

Chairman and Members of Yuen Long District Council
13/F, Yuen Long Government Offices,
No.2, Kiu Lok Square, Yuen Long, N.T.

By post and email: yldcadm@yldc.had.gov.hk

Missing and sub-standard pedestrian connections in the Yuen Long District

Dear Sirs and Madams

Our campaign 'Missing Links' began a year ago with the objective of improving pedestrian connections in Hong Kong. Via our website (www.missinglinks.hk), the public has identified locations where footpaths or crossings are either missing, narrow or sub-standard.

We are bringing a secondary relevant locations identified by the community to your attention and we would be grateful if Transport Department and the Yuen Long District Council would work together to improve these pedestrian connections for the benefits of residents and visitors of the Yuen Long District.

Enclosed please find a list of locations with photos and information. Please feel free to contact Mr. Leung at 3104-2766 or denis@designinghongkong.com if you have any questions. Keep us posted on the result so that we can inform the public accordingly.

Yours sincerely,

Paul Zimmerman, CEO of Designing Hong Kong

Encl. Maps and photos of 1 Missing Link

創建 Designing HongKong 邊度冇路行? www.MissingLinks.hk 香港

1.

Location: Castle Peak Road (Ping Shan)
Problem: Missing crossing
Description: Missing crossing to connect the bus stop and Light Rail Transit station, the distant footbridge is inconvenient for users
Suggestion: Provide zebra crossing, Belisha beacon, road marking and signs for cars to slow down

位置: 青山公路 (屏山段)
問題: 缺乏過路處
詳情: 缺乏過路處連接巴士站與輕鐵站，遠處的行人天橋並不方便乘客直接行走
建議: 提供斑馬綫、斑馬線指示燈及道路標記，並增設慢駛告示牌

